			6/28
United State	es Environmental Protection Agenc Washington, D. C. 20460	γ	Form Approved
SEPA NPDES Comp	oliance Inspection	n Report	OMB No. 2040-0003 Approval Expires 7-31-85
Sect	ion A: National Data System	Coding	
Transaction Code NPDES 1 2 5 3 M I 0 0 0 2 3 8 1 11	1289062817	Inspection Type Inspection 19 19 19	
	Remarks		
Reserved Facility Evaluation Rating 67 69 705 7	BI OA 1 1 72 4 73	Reserved	80
	Section B: Facility Data		
Name and Location of Facility Inspected PENNWALT COLPORATION		Entry Time AM PM	Permit Effective Date 9-15-88
4656 BIDDLE AVENUE WYANDOTTE, MICHIGAN 48	912	Exit Time/Date 6-28-9	Permit Expiration Date 39 10-1-92
Name(s) of On-Site Representative(s)	Title(s)	<u> </u>	
LIDUEL MONATTE	MANAGRE ENVIRON Suprevisur, Labor	MENTAL APPAIRS -	Phone No(s) (3/3) 246 - 2030 285 - 9200 246 - 2070
THOMAS OUERGAARD	SUPERVISOR OF C	Ham1875 -	246 - 2070
ERIC PALLA	WASTENATAL A		285 - 9200
Name, Address of Responsible Official FRANK DI MAGGIO	Title PLANT NANAG	SEL	
(SAME 45 ABOVE)	Phone No. (3/3) 285-9	200	Contacted Yes No
	C: Areas Evaluated During In	•	
S Permit S Flow Measure	I = Marginal, U = Unsatisfactor	atment	Operations & Maintenance
S Records/Reports S Laboratory		iance Schedules	Sludge Disposal
S Facility Site Review S Effluent/Rece		onitoring Program	Other:
	ndings/Comments (Attach ad	<u></u>	Other.
NO LABORATORY DEFICIENCIE	S WERE UNCO	JERED WHICH O	COULD
EXPLAIN THE UNACCEPTABL	E RESULTS FO	R BODS, TOTAL	Suspanded
SOLIDS AND TOTAL ZING	IN THE DM	R-QA OOB CHE	CK SAMASS,
DATA REPORTED BY THIS PE	emittee und	ER THE NPDES	PROGRAM
SHOULD BE CUMSIDERED 1	ACCURATE AND	VALID.	
	US EPA RECORDS CENTER	REGION 5	
		eret inet inet	
	ncy/Office/Telephone 454		Date

NPDES No	MI 00023	281
Facility Name _	PENNWALT	CORPORATION
City and State	WYANDO	TTE, MICHIGAN
Date of Inspect	tion JUNE	28, 1989

.

RECORDS, REPORTS, AND SCHEDULES CHECKLIST

A. PERMIT VERIFICATION

YES	NO	N/A	INSPECTION OBSERVATION CONTAINED IN PERMIT
Х			1. Correct name and mailing address of permittee.
X			2. Facility is as described in permit.
X			3. Notification has been given to EPA. State of new, different, increased discharges.
		X	4 Accurate records of influent volume are maintained, when appropriate.
X			5. Number and location of discharge points are as described in the permit.
X			6. Name and location of receiving waters are correct.
X			7. Ail discharges are permitted.

B. RECORDKEEPING AND REPORTING EVALUATION

		B. RECORDREPING AND REPORTING EVALUATION
		RECORDS AND REPORTS ARE MAINTAINED AS REQUIRED BY PERMIT
X		1 Ail required information is available, complete, and current; and
X		2. Information is maintained for required period.
		3. Analytical results are consistent with the data reported on the IMR's.
		4. Sampling and Analysis Data are adequate and include:
X		a. Dates, times, location of sampling
X		b. Name of individual performing sampling
$\overline{}$		c. Analytical methods and techniques
X X		d. Results of analysis
X		e. Dates of analysis
X		f. Name of person performing analysis
	X	g. Instantaneous flow at grab sample stations
		5. Monitoring records are adequate and include
Χ		a. Flow, pH, D.O., etc, as required by permit
X		b. Monitoring charts
X		6. Laboratory equipment calibration and maintenance records are adequate.
	X	7. Plant Records are adequate* and include
		a. O&M Manual
		b. "As-built"engineering drawings
		c. Schedules and dates of equipment maintenance and repairs
	11	d. Equipment supplies manual
		e. Equipment data cards
		* Required only for facilities built with Endered construction great funds

RECORDS, REPORTS, AND SCHEDULES CHECKLIST

B. Recordkeeping and Reporting Evaluation (continued)

YES	NO	N ∕A	8. Pretreatment records are adequate and included:
			a. Industrial Waste Ordinanace (or equivelant documents)
			b. Inventory of industrial waste contributors, including:
			Compliance records
	-		2. User charge information
			9. SPCC properly completed, when required.
			10. Best Management Practices Program available, when required.

C. Compliance Schedule Status Review

	X	THE PERMITEE IS MEETING THE COMPLIANCE SCHEDULE
		The permitee has obtained necessary approvals to begin construction.
		2. Financing arrangements are completed.
		3. Contracts for engineering services has been executed.
		4. Design plans and specifications have been completed.
		5. Construction has begun.
		6. Construction is on schedule.
		7. Equipment acquisition is on schedule.
		8. Construction has been completed.
		9. Start-up has begun.
		10. The permittee has requested an extension of time.
		11. The permittee has met compliance schedule.

RECORDS, REPORTS, AND SCHEDULES CHECKLIST

D. POTW Pretreatment Requires Review

YES	NO	%	THE FACILITY IS SUBJECT TO PRETREATMENT REQUIREMENTS	
		1	1. Status of POTW Pretreatment Program	
			a. The POTW Pretreatment Program has been approved by EPA. (If not, is approval in progress?)	
			 b. The POTW is in compliance with the Pretreatment Program Compliance Sched (If not, what is due, and intent of the POTW to remedy) 	edule
			2. Status of Compliance with Categorical Pretreatment Standards.	
			all now many industrial users of the POTW are subject to Federal or State Pretreatment Standards?	
			a Are these industries aware of their responsibility to comply with applicable standards?	
			a. Have paseline monitoring reports (403.12) been submitted for these industries	s?
			Have categorical industries in noncompliance (on EMR reports) submitted compliance schedules?	
			in how many categorical industries on compliance schedules are meeting the schedule deadlines?	е
			d. If compliance deadlines has passed, have all industries submitted 90 day compliance reports?	·
			e. Are all categorical industries submitting the required semiannual report?	
			f. Are all new industrial discharges in compliance with new source pretreatment standards?	
			g. Has the POTW submitted its annual pretreatment report?	
			h. Has the POTW taken enforcement action against noncomplying industrial users	rs?
			i. Is the POTW conducting inspections of industrial contributors?	
		V	 Are the industrial users subject to Prohibited Limits (403.5) and local limits more stringent tha EPA in compliance? (If not , explain why, including need for revision limits.) 	

FACILITY SITE REVIEW CHECKLIST

YES	NO	N/A	Standby power or other equivalant provision is provided.
X			2. Adequate alarm system for power or equipment failures is available.
		X	POTW handles and disposes of sludge according to applicable Federal, State, and local regulators.
X			4. All treatment units, other than back-up units, are in service.
X			5. Procedures for facility operation and maintenance exist.
X			6. Organization plan (chart) for operation and maintenance is provided.
X			7. Operating schedules are established.
X			8. Emergency plan for treatment control is established.
			Operating management control documents are current and include.
X			a. Operating report
X			b. Work schedule 24HC5/DA-1
X			c. Activity report (time cards)
		X	10. Maintenance record system exists and includes:
			a. As-built drawings
			b. Shop drawings
			c. Construction specifications
			d. Maintenance history
		4	e. Maintenance costs
X			11. Adequate number of qualified operators are on hand.
X			12. Established procedures are available for training new operators.
X			Adequate spare parts and supplies inventory and major equipment specifications are maintained.
X			Instruction files are kept for operation and maintenance of each item of major equipment.
X			15. Operation and maintenance manual is available.
		X	16. Regulatory agency was notified of bypassing. NOT POSSIDLA TO BY-PASS (Dates)

FACILITY SITE REVIEW CHECKLIST

YES	×	N/A	17. Hydraulic and/or organic overloads are experienced. Reason for overloads
X		-	18. Up-to-date equipment repair records are maintained.
		X	19. Dated tags show out of service equipment.
X			20. Routine and preventive maintenance are scheduled/performed on time.

PERMITTEE SAMPLING INSPECTION CHECKLIST

A. Permittee Sampling Evaluation

XX S	NO	N/A	Samplings are taken at sites specified in permit.
X			2. Locations are adequate for representative samples.
		X	3. Flow proportioned samples are obtained where required by permit. NOT 5747ED PERMIT
X	_		4. Sampling and analysis completed on parameters specified by permit.
X			5. Sampling and analysis done in frequency specified by permit.
X			6. Permittee is using method of sample collection required by permit. Required Method: If not, method being used is: () Grab : Manual composite Automatic composite
X			7. Sample collection procedures are adequate:
X			a. Samples refrigerated during compositing
X			b. Proper preservation technique used
X			c. Container and sample holding times before analyses conform with 40 CFR 136.3
		X	Monitoring and analyses are performed more often than required by permit. If so, results reported in permittee's self-monitoring report.

B. Sampling Inspection Procedures and Observations

X	Grab samples obtained
	Composite sample obtained Composite frequency Preservation
	3. Sample refrigerated during compositing.
	4. Flow proportioned sample obtained.
	5. Sample obtained from facility sampling device.
	6. Sample representative of volume and nature of discharge.
	7. Sample split with permitee.
b	8. Chain of custody procedures employed.

FLOW MEASUREMENT

A. Flow Measurement Inspection Checklist-General

YES NO	O N/A	1. Primary flow measurement device is properly installed and maintained.
X		2. Flow records are properly kept.
X		3. Sharp drops or increases in flow value are accounted for.
X	(_	4. Actual flow discharge is neasured.
X		5. Influent flow is measured before all return lines. Pumps
	X	6. Effluent flow is measured after all lines.
X		7. Secondary instruments (totalizers, recorders, etc., are properly operated and maintained
\times		8. Spare parts are stocked.
X	X	7. Secondary instruments (totalizers, recorders, etc., are properly operated and maintained

B. Flow Measurement Inspection Checklist-Flumes

X	 Flow intering flume appears reasonably well distributed across the channel and free of turbulence, boils, or other distortions. 	
	2. Cross-section velocities at entrance are relatively uniform.	
	3. Flume is clean and is free of debris or deposits.	
	4. All dimensions of flume are accurate.	
	5. Side walls of flume are vertical and smooth.	
	6. Sides of flume throat are vertical and parallel.	
	7. Flume head is being measured at proper location.	
	8. Measurement of flume head is zeroed to flume crest.	
	9. Flume is of proper size to measure range of existing flow.	
	10. Flume is operating under free-flow conditions over existing range of flows.	

EFFLUENT FLOW DISCITIRGE (BEING REVIEWED BY DNR)

FLOW MEASUREMENT

C. Flow Measurment Inspection Checklist - Weirs

				1. What type of weir is being used?	
YES	NO	2	A	2. The weir is exactly level.	
				3. The weir plate is plumb and its top edges are sharp and clean.	
				4. There is free access for air below the nappe of the weir.	
				Upstream channel of weir is straight for at least four times the depth of water level, and free from disturbing influences.	
				6. The stilling basin of the weir is of sufficient size and clear of debris.	
				7. Head measurements are properly made by facility personnel.	
		V		8. Proper flow tables are used by facility personnel.	

D. Flow Measurement Inspection Checklist - Other Flow Devices

×

		1. Type of flowmeter used: DIFFELDWTUAL FLOW METER			
		2. What are the most common problems that the operator has had with the flowmeter?			
		3. Measure Wastewater flow: mgd; Recorded flow: mgd; Error %			
		4. Design flow: mgd.			
X		5. Flow totalizer is properly calibrated.			
		6. Frequency of routine inspection by proper operator: 6NG /day.			
		7. Frequency of maintenance inspections by plant personnel:/year.			
		8. Frequency of flowmeter calibration: /month.			
X		9. Flow measurement equipment adequate to handle expected ranges of flow rates.			
	X	10. Venturi meter is properly installed and calibrated.			
	X	11. Electromagnet flowmeter is properly calibrated.			

LABORATORY QUALITY ASSURANCE CHECKLIST

A. General

Y 55	NO	N/A	Written laboratory quality assurance manual is available.
•			

B. Laboratory Procedures

Χ			EPA approved analytical testing procedures are used.
		X	2. If alternative analytical procedures are used, proper approval has been obtained.
Χ			3. Calibration and maintenance of instruments and equipment is satisfactory.
X			4. Quality control procedures are used.
X			5. Quality control procedures are adequate.
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		6 Duplicate sample are analyzed 30+ % of time. S. メルル,
		X	7 Spiked samples are used % of time.
			8. Commercial laboratory is used: Name: YOFK LABS Address: CHICAGO ICC Contact: Phone:

C. Laboratory Facilities and Equipment

X	Proper grade distilled water is available for specific analysis.	
X	2. Dry, uncontaminated compressed air is available.	
X	3. Fume hood has enough ventilation capacity.	
X	4. The laboratory has sufficient lighting.	
X	5. Adequate electrical sources are available.	
X	6. Instruments/equipment are in good condition.	
X	7. Written requirements for daily operation of instruments are available.	

LABORATORY QUALITY ASSURANCE CHECKLIST (continued)

C. Laboratory Facilities and Equipment (continued)

x¥s	NO	N/A	8. Standards are available to perform daily check procedures.			
X			9. Written trouble-shooting procedures for instruments are available.			
X			10. Schedule for required maintenance exists.			
X			11. Proper volumetric glassware is used.			
X	_		12. Glassware is properly cleaned.			
X			13. Standard reagents and solvents are properly stored.			
X			14. Working standards are frequently checked.			
X			15. Standards are discarded after shelf life has expired.			
X			16. Background reagents and solvents run with every series of samples.			
X			17. Written proedures exist for cleanup, hazardous response methods, and applications of correction methods for reagents and solvents.			
X			18. Gas cylinders are replaced at 100-200 psi. A.A. meracs			

D. Laboratory's Precision, Accuracy, and Control Procedures

X	A minimum of seven replicates is analyzed for each type of control check and this information is on record.
X	Plotted precision and accuracy control charts are used to determine whether valid, questionable, or invalid data are being generated from day to day.
X	Control samples are introduced into the train of actual samples to ensure that valid data is being generated.
X	4. The precision and accuracy of the analyses are good.

LABORATORY QUALITY ASSURANCE CHECKLIST (continued)

E. Data Handling and Reporting

yrs	NO	N/A	Round-off rules are uniformly applied.		
X			2. Significant figures are established for each analysis.		
X			3. Provision for cross-checking calculations is used.		
X			4. Correct formulas are used to reduce to simplest factors for quick, correct calculations.		
X			Control chart approach and statistical calculations for quality assurance and report are available and followed.		
X			 Report forms have been developed to provide complete data documentation and permanent records and to facilitate data processing. 		
X			7. Data are reported in proper form and units.		
X			Laboratory records are kept readily available to regulatory agency for required period of time		
X			9 Laboratory notebook or preprinted data forms are commonantly books to provide good documentation.		
X			10. Efficient filing system exists enabling prompt channeling of report copies.		

F. Laboratory Personnel

X	The analyst has appropriate training
X	2. The analyst follows the specified procedures
X	3. The analyst is skilled in performing analyses

Page	of
uyc	01

II. SAMPLING AND PRESERVATION

Laboratory	PENNWALT	Unit
------------	----------	------

Provide a listing of sample containers and preservatives (icing or refrigeration are a preservative) used for chemical analyses. For each container and preservative combination provide a listing of parameters routinely analyzed and their normal holding times. Use comments to differentiate programs, if necessary, or to note any special container precleaning used. If this information is already documented, please provide it instead of completing this section.

(1 8 7	Container*			 	Holding		т
N25	(also state Preservation		Para	neters	Time	Comments	
8725	volume)	FRUM CRZ BUTTE			(normal)		<u>ب</u> ل
	D.O	FRUM CL2 34MD	-15		< 30M/N	GRABS	
	PH			A = 4.5			+
	Cla	NO AIR SPACIE L			(50M/N	LOW CO2 ANYWAY	+′
	* 5450. Y1 SOLIDS	NP	1 GAG		21HR		
\ \	* 10W		7,5	1			+
	12 BODS				4/2/te		
	CHLURIDAS	ω			<1HR		<u>†</u>
	* 200	ALIQUOTE					+
•	ZINC	PLASSIC BUTTLE					
//	PHENOL	1 ml H2504 NOTICAD		Bons		TO CONTRACTOR YOLK LASS IN CHICAGO	×
	NH3	NOT ILED NO	V		RIN WITHIN I HA	MONITUL	
	TEMP.						
	N R	NAY BE DONE	In-ite	ons L			<u>-</u>
1							•

^{*} High Density Polyethlene (HDP), Low Density Polyethylene (LDP), Glass (G), Reusable (R), Disposable (D).

III. TEST PROCEDURES USED FOR POINT SOURCE MONITORING including COMPLIANCE MONITORING FOR THE NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM

Laboratory	PENNWALT				

F			REFERENCE			
SPECIFIC PARAMETER	METHOD DESCRIPTION	STD. METHODS	USEPA METHODS	ASTM METHODS	OTHER	1
PH	COEN MU DH/ JOP 135 REGORDS GTDINATION 2 PRICE METHOD COEN MU DARK BOX CAB RACIS SPECFIC ION METTER TIME 4DIL / 3 SAED / 1 BCK MAKE OWN SKEED 14 BCK PICLUS DAILY	wr 16th				
Cl2	SPECFIC ION METER . TIME					
D.C. BODS	4DIL 35BED / 1BEK MAKE OWN SKEED HACK PILLUS DAILY	SUD STD F	un wa	say		
545P 50CIDS 442	TEMP@ 107 6/28/39 NORMALLY TEMP@ 107 6/28/39 NORMALLY TOP NOT THE MITTO & UNA, NO , Out / 105 TO -1	156 103 -109	6.5	5 570 N NAS	e y	
CHLORIDA	my ND7 TITE MITTON K Charling Jours / FASTP -1	SIP Cl	a Sping	once/m	-	K
ZINC						
PHENOL	CONTERCT GC					
	DIST W/ BUCH 320 (BTEAN DISTILL) NHS					
NH3	INTO IND. BOLIC ACID	b				
	GTP DISTILLED JUER H250 U TITARTION					

TEMP.